


HS150 Installation - HS153 (slot mount)



- 1 Slide stopper off of sensor cable.



- 2 Slide sensor cable through stand.




- 3 Slide sensor cable through fixture.




- 4 Slide sensor cable through wingnut as illustrated. Wingnut must be attached in the exact orientation as illustrated.




- 5 Plug power supply into sensor cable. Plug power supply into outlet.




- 6 Slide stopper back onto sensor cable.



- 7 Slide both stand screws through wingnut.



- 8 Tighten both screws onto stand screw.



- 9 Slide sensor cable through top of stand.